

ENGINEERING CHANGE NOTICE **DART AEROSPACE LTD**

Date: 09.02.05	Job No.: P00582	ADR Yes/No: Yes	ADR Date: 09.02.05	ECN #: 09- 523
Product No.: D350-589		Created By: HS	Approved By: <i>[Signature]</i>	
Product Name: Side Doors		Checked By: <i>[Signature]</i>	General Manager Approval: <i>[Signature]</i>	

Distribution	Reqd	Resp	Initial / Date	Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL	<i>[Signature]</i> 09.02.11	DQA / QA Coord	N		
Production Engineering Coord	Y	EC	<i>[Signature]</i> 09.02.11	QC Coordinator	N		
Production Document Control	Y	JLB	<i>[Signature]</i> 09.02.11	Marketing	Y	SW	SW 09.02.11
Customer Technical Support	Y	DS	<i>[Signature]</i> 09.02.11	Customer Order Processing	N		

Reason for Change: Customers informed us that there is no provision for moving the door open switch and that the sliding door interferes with the upper forward latch.

Documents Affected:

DSI 9446 Rev. A	D3894 Rev. A
DSI 9447 Rev. A	D3895 Rev. A

PARTS MUST COMPLY ☒ **PREVIOUS PARTS SATISFACTORY** ☐

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	Y	SW	Air Methods/ Coastal Helicopters	SW 09.04.28
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	Y	KJ		09.02.10 <i>[Signature]</i>
5	Update Product Compatability Matrix	N			
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		09.02.11 <i>[Signature]</i>
9	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		09.02.10 <i>[Signature]</i>
10	Update Controlled PDF Files	Y	KJ		09.02.10 <i>[Signature]</i>
11	Update Master Document List (MDL)	N	KJ	MDL D350-589 Rev.	N/A <i>[Signature]</i>
12	Update Document Record (DR)	Y	KJ	Rev. H	09.02.10 <i>[Signature]</i>
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	Y	KJ		09.02.10 <i>[Signature]</i>
16	Update / Verify ARC Database	Y	KJ	#19	09.02.10 <i>[Signature]</i>
17	Create / Update Change Record Form	Y	KJ		09.02.10 <i>[Signature]</i>
18	Create / Update PPP's	Y	KJ		09.02.10 <i>[Signature]</i>
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ	Add ADR	09.02.10 <i>[Signature]</i>
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		09.02.10 <i>[Signature]</i>
22					
23					

Description / Action:

- Door Open switch bracket and door doubler were designed and DSIs produced for the installation of both of these items
- Create estimate for the production of DSI 9446-011, DSI 9447-011, D3894-1 and D3895-1
- Send parts out at no charge to each customer who has purchased the D35X-589-041/-042/-043 side doors.
- 1x D3894-1 and 1x D3895-1 should be added to the pick list for D35X-589-041/-042/-043 side doors
- D35X-589-041/-042/-043 now at CHG 3 & DSI 9446-011, DSI 9447-011 @ CHG 001
- DSI 9446/9447 need to be added to Blue File Paperwork
- Add 1x D3894-1, 1x D3895-1, 1 copy of DSI 9446, 1 copy of DSI 9447 to all D35X-589-041/-042/-043 kits in stock or in production

ECN Verified & Complete: *[Signature]*

Date: 09/05/04